

Technical Bulletin

Bulletin No.: PRO-10-03

Effective Date: 5/15/83

Cancels: N/A

Page: 1 of 1

Subject: INSTRUCTION SHEET AMENDMENT CRUISE CONTROL KIT 209893 FREIGHTLINER CAB-OVER ENGINE

The purpose of this bulletin is to emphasize the importance of the position of the two $\frac{1}{4}$ " – 20 X $\frac{3}{4}$ " cap screws referred to on Page 7, Instruction 7 and illustrated in Figure 5 of BWS-808 Kit 209893 Freightliner Cab-Over Engine.

These two bolts must be installed as shown, with head of bolt on the backside of the throttle lever bracket to allow for adequate clearance throughout the entire travel of the bell crank.

